

Device Errata

Skywire® Modem

NimbeLink // Products
Published // June, 2015



© NimbeLink Corp. 2018. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink and Skywire are registered trademarks of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

Table of Contents

| | |
|--|----------|
| Table of Contents | 2 |
| Applies to NimbeLink Part Numbers | 3 |
| Affected Part Numbers | 3 |
| Applications Affected | 3 |
| How to Identify PCB Revision | 3 |
| Workarounds | 4 |
| Board Rework | 4 |
| Contact | 5 |
| Version Information | 5 |

1 Applies to NimbeLink Part Numbers

| Affected Part Numbers |
|-----------------------|
| NL-SW-1xRTT-V |
| NL-SW-1xRTT-A |
| NL-SW-EVDO-V |
| NL-SW-EVDO-A |
| NL-SW-GPRS |
| NL-SW-HSPAP |
| NL-SW-HSPAPE |
| NL-SW-HSPAPG |
| NL-SW-LTE-TSVG |
| NL-SW-LTE-TEUG |
| NL-SW-LTE-TNAG |


2 Applications Affected

This Errata affects applications requiring use of the UART CTS hardware flow control output from the Skywire modem. The UART CTS signal (Pin 12 on the Skywire interface) is not connected on NimbeLink PCBs prior to PCB revision F. This Errata does not affect your design if any of the following are true:

- 1) Skywire PCB is revision F or higher
- 2) USB is used for communication instead of UART
- 3) Hardware design does not connect to Skywire CTS pin
- 4) Design does not implement hardware flow control in hardware and/or software
- 5) Software design implements software flow control (XON/XOFF)

3 How to Identify PCB Revision

The PCB revision is found on the bottom side of the modem between J1 (Skywire interface connector) and J3 (Micro-SIM socket). The revision is written in white silkscreen and is of the form 20001 rev X.




4 Workarounds

For customers that have affected product, these alternatives may permanently alleviate the effects of the Errata in your application.

- 1) Use USB interface instead of UART
- 2) Use software flow control (XON/XOFF) instead of hardware flow control
- 3) Modify existing modem to correct for CTS Errata (see section 5)

5 Board Rework

The Errata can be repaired on affected product by soldering a wire to the underside of the modem. The wire must connect Skywire interface pin 12 to U2 pin 18. Adding this wire will not invalidate the product warranty, however, poor workmanship can damage the modem and invalidate the warranty.



6 Contact

For further information please contact NimbeLink Technical Support:
product.support@nimbelink.com.

7 Version Information

| | | | | |
|---|-----|---------------|--|------------|
| A | RGL | Initial draft | | 05/28/2015 |
| B | | | | 00/00/00 |